Errata: CS5532/34-BS rev D Silicon Errata

(Reference CS5532/34-BS data sheet revision DS755F2 dated MAY '07).

Description:

The clock generation circuitry (the on-chip oscillator and the comparator that follows it) may fail to generate a reliable clock for the converter under some bipolar power supply conditions.

Work Around:

To ensure proper operation when using the on-chip gate oscillator with the converter powered from bipolar supplies, the following restriction is to be followed:

VD+ must be more positive than +3.2 V and VA- cannot be more negative than -[(VD+)-0.3].

For example:

If VD+ = 3.3 V, then VA- cannot be more negative than -[3.3-0.3] or –3.0 V.

If the converter is operated from a bipolar supply of:

VA+ = VD+ = +3.3V and VA- = -3.3 V

or:

VA+= VD+ = 3.0 V and VA- = -3.0 V

the converter should be driven from an external clock source.

CONTACTING CIRRUS LOGIC SUPPORT

For a complete listing of direct Distributor, Sales, and Sales Representative contacts, visit the Cirrus Logic website at http://www.cirrus.com.