
Errata: CS42L52 Rev. B0 Silicon

Reference the CS42L52_DS680PP1 Data Sheet

- ◆ The VP Input Current During Reset does not meet data sheet specification. During reset, the current through the VP supply may exceed 200 uA when VP > 3.7 V.

Contacting Cirrus Logic Support

For all product questions and inquiries, contact a Cirrus Logic Sales Representative.
To find the one nearest you, go to <http://www.cirrus.com>