

Errata: CS35L00 Rev. B0 Silicon

(Reference CS35L00_DS906PP1 Data Sheet)

WARNING: While operating in either HD or FHD mode, connecting either or both of the OUT± pins to VBATT, GND, or each other may result in permanent damage to the device.

Contacting Cirrus Logic Support

For all product questions and inquiries, contact a Cirrus Logic Sales Representative.
To find the one nearest you, go to <http://www.cirrus.com>